(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes levees	, and	Aquifer-fed excavated pond	s
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
11B: Colo	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill	0.30
Ely	Somewhat limited Seepage	0.70	Somewhat limited Depth to saturated zone Piping	0.43	Cutbanks cave  Somewhat limited Slow refill  Deep to water Cutbanks cave	0.10 0.30 0.25 0.10
3B: Olmitz	Somewhat limited Seepage	0.70	Somewhat limited Piping	0.41	Very limited Deep to water	1.00
Colo	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill	0.30
Vesser	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone Piping	1.00	Cutbanks cave Somewhat limited Slow refill Cutbanks cave Deep to water	0.10 0.30 0.10 0.01
23C: Arispe	Somewhat limited Seepage	0.70	Somewhat limited Depth to saturated zone	0.43	Somewhat limited Slow refill Deep to water Cutbanks cave	0.30 0.25 0.10
23C2: Arispe	Somewhat limited Seepage	0.70	Somewhat limited Depth to saturated zone	0.43	Somewhat limited Slow refill Deep to water Cutbanks cave	0.30 0.25 0.10
24D2: Shelby	Somewhat limited Seepage Slope	0.05	Not limited		Very limited Deep to water	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes levees	, and	Aquifer-fed excavated pond	s
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
24E2: Shelby	Somewhat limited Seepage Slope	0.05	Not limited		Very limited Deep to water	1.00
ID: Sparta	Very limited Seepage	1.00	Very limited Seepage	1.00	Very limited Deep to water	1.00
51: Vesser	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone Piping	1.00	Somewhat limited Slow refill Cutbanks cave	0.30
54: Zook	Somewhat limited Seepage	0.01	Very limited Depth to saturated zone Hard to pack	1.00	Somewhat limited Slow refill Cutbanks cave	0.95
54+: Zook	Somewhat limited Seepage	0.01	Very limited Depth to saturated zone Hard to pack	1.00	Somewhat limited Slow refill Cutbanks cave	0.30
88D2: Douds	Very limited Seepage Slope	1.00	Somewhat limited Seepage	0.08	Very limited Deep to water	1.00
58E2: Douds	Very limited Seepage Slope	1.00	Somewhat limited Seepage	0.08	Very limited Deep to water	1.00
55D: Lindley	Somewhat limited Seepage Slope	0.05	Somewhat limited Piping	0.41	Very limited Deep to water	1.00
55E: Lindley	Somewhat limited Seepage Slope	0.05	Somewhat limited Piping	0.41	Very limited Deep to water	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes levees	, and	Aquifer-fed excavated pond	ls
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
65E2: Lindley	Somewhat limited Seepage Slope	0.05	Somewhat limited Piping	0.41	Very limited Deep to water	1.00
55G: Lindley	Somewhat limited Slope Seepage	0.45	Somewhat limited Piping	0.41	Very limited Deep to water	1.00
76B: Ladoga	Somewhat limited Seepage	0.70	Not limited		Very limited Deep to water	1.00
76C: Ladoga	Somewhat limited Seepage	0.70	Not limited		Very limited Deep to water	1.00
76C2: Ladoga	Somewhat limited Seepage	0.70	Not limited		Very limited Deep to water	1.00
76D: Ladoga	Somewhat limited Seepage Slope	0.70	Not limited		Very limited Deep to water	1.00
76D2: Ladoga	Somewhat limited Seepage Slope	0.70	Not limited		Very limited Deep to water	1.00
80D: Clinton	Somewhat limited Seepage Slope	0.70	Not limited		Very limited Deep to water	1.00
80D2: Clinton	Somewhat limited Seepage Slope	0.70	Not limited		Very limited Deep to water	1.00
130: Belinda	Somewhat limited Seepage	0.01	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill	0.30
					Cutbanks cave	0.10

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes levees	, and	Aquifer-fed excavated pond	ls
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
31B: Pershing	Somewhat limited Seepage	0.05	Somewhat limited Depth to saturated zone	0.43	Somewhat limited Slow refill	0.95
					Deep to water Cutbanks cave	0.25
31C: Pershing	Somewhat limited Seepage	0.05	Somewhat limited Depth to saturated zone	0.43	Somewhat limited Slow refill	0.95
			Bacaracca Zone		Deep to water Cutbanks cave	0.25
l32B: Weller	Not limited		Somewhat limited Hard to pack Depth to	0.71	Very limited Slow refill Deep to water	1.00
			saturated zone		Cutbanks cave	0.10
l32C: Weller	Not limited		Somewhat limited Hard to pack Depth to	0.71	Very limited Slow refill Deep to water	1.00
			saturated zone		Cutbanks cave	0.10
.33: Colo	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill	0.30
22					Cutbanks cave	0.10
.33+: Colo	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill	0.30
00-					Cutbanks cave	0.10
33B: Colo	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill	0.30
					Cutbanks cave	0.10

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes, and levees		Aquifer-fed excavated ponds	
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
79D2: Gara	Somewhat limited Seepage Slope	0.05	Not limited		Very limited Deep to water	1.00
79E2: Gara	Somewhat limited Seepage Slope	0.05	Not limited		Very limited Deep to water	1.00
79F: Gara	Somewhat limited Slope Seepage	0.18	Not limited		Very limited Deep to water	1.00
79F2: Gara	Somewhat limited Slope Seepage	0.18	Not limited		Very limited Deep to water	1.00
92D2: Adair	Somewhat limited Seepage Slope	0.05	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave Deep to water	0.95 0.10 0.01
11: Edina	Not limited		Very limited Depth to saturated zone Hard to pack	1.00	Somewhat limited Slow refill Cutbanks cave	0.30
20: Wodaway	Somewhat limited Seepage	0.70	Very limited Piping	1.00	Somewhat limited Deep to water Slow refill Cutbanks cave	0.81 0.30 0.10
22C: Clarinda	Not limited		Very limited Depth to saturated zone Hard to pack	1.00	Very limited Slow refill Cutbanks cave	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes levees	, and	Aquifer-fed excavated pond	ls
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
222C2: Clarinda	Somewhat limited Seepage	0.01	Very limited Depth to saturated zone Hard to pack	1.00	Somewhat limited Slow refill Cutbanks cave Deep to water	0.99 0.10 0.01
22D2: Clarinda	Somewhat limited Seepage Slope	0.01	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave	0.99
223C2: Rinda	-	0.01	Wery limited Hard to pack Depth to saturated zone	1.00	Deep to water  Very limited Slow refill Cutbanks cave Deep to water	1.00 0.10
223D2: Rinda	Somewhat limited Slope	0.01	Very limited Hard to pack Depth to saturated zone	1.00	Very limited Slow refill Cutbanks cave Deep to water	1.00 0.10 0.01
260: Beckwith	Somewhat limited Seepage	0.05	Very limited Depth to saturated zone Hard to pack	1.00	Somewhat limited Slow refill Cutbanks cave	0.30
263: Okaw	Not limited		Very limited Depth to saturated zone Hard to pack	1.00	Somewhat limited Slow refill Cutbanks cave	0.30
273C: Olmitz	Somewhat limited Seepage	0.70	Somewhat limited Piping	0.41	Very limited Deep to water	1.00
779: Taintor	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone Hard to pack	1.00	Somewhat limited Slow refill Cutbanks cave	0.30

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes levees	, and	Aquifer-fed excavated pond	.s
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
280: Mahaska	- Somewhat limited Seepage	0.70	Somewhat limited Depth to saturated zone	0.43	Somewhat limited Slow refill Deep to water Cutbanks cave	0.30 0.25 0.10
281B: Otley	- Somewhat limited Seepage	0.70	Not limited		Very limited Deep to water	1.00
281C: Otley	- Somewhat limited Seepage	0.70	Not limited		Very limited Deep to water	1.00
281C2: Otley	- Somewhat limited Seepage	0.70	Not limited		Very limited Deep to water	1.00
313D: Gosport	- Somewhat limited Depth to bedrock Slope	0.11	Somewhat limited Hard to pack Depth to saturated zone Thin layer	0.99	Very limited Slow refill Cutbanks cave Deep to water	1.00 0.10 0.02
313D2: Gosport	- Somewhat limited Depth to bedrock Slope	0.11	Somewhat limited Hard to pack Depth to saturated zone Thin layer	0.99	Very limited Slow refill Cutbanks cave Deep to water	1.00 0.10 0.02
313E: Gosport	- Somewhat limited Depth to bedrock Slope	0.11	Somewhat limited Hard to pack Depth to saturated zone Thin layer	0.99	Very limited Slow refill Cutbanks cave Deep to water	1.00 0.10 0.02
313E2: Gosport	- Somewhat limited Depth to bedrock Slope	0.11	Somewhat limited Hard to pack Depth to saturated zone Thin layer	0.99	Very limited Slow refill Cutbanks cave Deep to water	1.00 0.10 0.02

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes levees	, and	Aquifer-fed excavated pond	.s
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
313F: Gosport	Somewhat limited Slope Depth to bedrock	0.64	Somewhat limited Hard to pack Depth to saturated zone Thin layer	0.99 0.95 0.86	Very limited Slow refill Cutbanks cave Deep to water	1.00 0.10 0.02
362: Haig	Somewhat limited Seepage	0.05	Very limited Depth to saturated zone Hard to pack	1.00	Somewhat limited Slow refill Cutbanks cave	0.30
364B: Grundy	Not limited		Somewhat limited Depth to saturated zone Hard to pack	0.95	Very limited Slow refill Cutbanks cave Deep to water	1.00 0.10 0.02
419D2: Vanmeter	Somewhat limited Depth to bedrock Slope	0.11	Somewhat limited Depth to saturated zone Thin layer	0.95	Very limited Slow refill Cutbanks cave Deep to water	1.00 0.10 0.02
419E2: Vanmeter	Somewhat limited Depth to bedrock Slope	0.11	Somewhat limited Depth to saturated zone Thin layer	0.95	Very limited Slow refill Cutbanks cave Deep to water	1.00 0.10 0.02
423D2: Bucknell	Somewhat limited Slope	0.01	Very limited Depth to saturated zone Hard to pack	1.00	Very limited Slow refill Cutbanks cave Deep to water	1.00 0.10 0.01
424E2: Lindley	Somewhat limited Seepage Slope	0.05	Somewhat limited Piping	0.59	Very limited Deep to water	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes, and levees		Aquifer-fed excavated pond	ls
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
eswick	Somewhat limited Seepage	0.05	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill	0.95
	Slope	0.01			Cutbanks cave Deep to water	0.10
5C: eswick	Somewhat limited Seepage	0.05	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill	0.95
					Cutbanks cave Deep to water	0.10
5D: eswick	Somewhat limited Seepage	0.05	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill	0.95
	Slope	0.01	saturated zone		Cutbanks cave Deep to water	0.10
25D2: Ceswick	Somewhat limited Seepage	0.05	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill	0.95
	Slope	0.01			Cutbanks cave Deep to water	0.10
28B: :ly	Somewhat limited Seepage	0.70	Somewhat limited Depth to saturated zone	0.43	Somewhat limited Slow refill	0.30
			Piping	0.20	Deep to water Cutbanks cave	0.25
52C: ineville	Not limited		Very limited Depth to saturated zone	1.00	Very limited Slow refill	1.00
					Cutbanks cave Deep to water	0.10
78G: Gosport	Somewhat limited Slope Depth to bedrock	0.36	Very limited Hard to pack Depth to	1.00	Very limited Slow refill Cutbanks cave	1.00
			saturated zone Thin layer	0.86	Deep to water	0.02

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes levees	, and	Aquifer-fed excavated pond	.s
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
Rock Outcrop	Not rated		Not rated		Not rated	
84: Lawson	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone Piping	1.00	Somewhat limited Slow refill Cutbanks cave Deep to water	0.30 0.10 0.01
94C2: Galland	Very limited Seepage	1.00	Not limited		Somewhat limited Deep to water Cutbanks cave	0.81
94D2: Galland	Very limited Seepage Slope	1.00	Not limited		Somewhat limited Deep to water Cutbanks cave	0.81
88: Koszta	Somewhat limited Seepage	0.70	Somewhat limited Depth to saturated zone	0.86	Somewhat limited Slow refill Cutbanks cave Deep to water	0.30 0.10 0.06
31C2: Pershing	Somewhat limited Seepage	0.05	Somewhat limited Hard to pack Depth to saturated zone	0.46	Somewhat limited Slow refill Deep to water Cutbanks cave	0.95 0.25 0.10
31D2: Pershing	Somewhat limited Seepage Slope	0.05	Somewhat limited Hard to pack Depth to saturated zone	0.46	Somewhat limited Slow refill Deep to water Cutbanks cave	0.95 0.25 0.10
32C2: Weller	Somewhat limited Seepage	0.05	Somewhat limited Depth to saturated zone	0.43	Somewhat limited Slow refill Deep to water Cutbanks cave	0.95 0.25 0.10

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes levees	, and	Aquifer-fed excavated pond	.s
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
732D2: Weller	Seepage	0.05	Somewhat limited Depth to saturated zone	0.43	Somewhat limited Slow refill	0.95
	Slope	0.01			Deep to water Cutbanks cave	0.25
792C2: Armstrong	Somewhat limited   Seepage	0.05	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill	0.95
					Cutbanks cave Deep to water	0.10
792D2: Armstrong	Somewhat limited Seepage	0.05	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill	0.95
	Slope	0.01	sacuraced zone		Cutbanks cave Deep to water	0.10
795D: Ashgrove	Somewhat limited Slope	0.01	Very limited Depth to saturated zone Hard to pack	1.00	Very limited Slow refill Cutbanks cave Deep to water	1.00 0.10 0.01
322D2: Lamoni	Somewhat limited Slope	0.01	Very limited Depth to saturated zone Hard to pack	1.00	Very limited Slow refill Cutbanks cave Deep to water	1.00
332C2: Weller	Somewhat limited Seepage	0.05	Somewhat limited Depth to saturated zone	0.43	Somewhat limited Slow refill Deep to water	0.95
876B: Ladoga	Somewhat limited Seepage	0.70	Not limited		Cutbanks cave  Very limited Deep to water	1.00
876C2: Ladoga	Somewhat limited   Seepage	0.70	Not limited		Very limited Deep to water	1.00

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

Map symbol and soil name	Pond reservoir ar	eas	Embankments, dikes levees	, and	Aquifer-fed excavated pond	ls
	Rating class and limiting features	Value	Rating class and limiting features	Value	Rating class and limiting features	Value
993D2: Gara	Somewhat limited Seepage Slope	0.05	Not limited		Very limited Deep to water	1.00
Armstrong	Somewhat limited Seepage Slope	0.05	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave Deep to water	0.95 0.10 0.01
993E2: Gara	Somewhat limited Seepage Slope	0.05	Not limited		Very limited Deep to water	1.00
Armstrong	Somewhat limited Seepage Slope	0.05	Very limited Depth to saturated zone	1.00	Somewhat limited Slow refill Cutbanks cave	0.95
1130: Belinda	Somewhat limited Seepage	0.01	Very limited Depth to saturated zone	1.00	Deep to water  Somewhat limited Slow refill  Cutbanks cave	0.01
1131C: Pershing	Somewhat limited Seepage	0.05	Somewhat limited Depth to saturated zone	0.43	Somewhat limited Slow refill Deep to water Cutbanks cave	0.95 0.25 0.10
1279: Taintor	Somewhat limited Seepage	0.70	Very limited Depth to saturated zone Hard to pack	1.00	Somewhat limited Slow refill Cutbanks cave	0.30
5020: Dumps	Not rated		Not rated		Not rated	
Pits	Not rated		Not rated		Not rated	

(The information in this table indicates the dominant soil condition but does not eliminate the need for onsite investigation. The numbers in the value columns range from 0.01 to 1.00. The larger the value, the greater the limitation. See text for further explanation of ratings in this table.)

Monroe County, Iowa

ating class and imiting features	Value	Rating class and limiting features  Not rated	Value	Rating class and limiting features  Not rated	Value
t rated		Not rated		Not rated	
t rated		Not rated		Not rated	
t rated		Not rated		Not rated	
t rated		Not rated		Not rated	
t	rated	rated	rated Not rated	rated Not rated	rated Not rated Not rated